

SERVICE BULLETIN NO. 168 - PIPER

IMMEDIATE ACTION

SERVICE  **BULLETIN**

NUMBER 168

January 16, 1959

SUBJECT: Nose Gear Retraction Assist Cord
MODELS AFFECTED: PA-24 and PA-24 "250"
Serial Numbers 24-1 to 24-503 inclusive

Due to the short service life of the elastic bungee cord which assists in the retraction operation of the nose gear strut, a coil spring and link arrangement shall replace the elastic cord installations on the above mentioned airplanes.

A modification kit, part number 754 205, can be obtained from your nearest Piper distributor free of charge until June 1, 1959. To secure this material free of charge it will be necessary that the aircraft serial number or numbers be included on all purchase orders.

Warrenty labor of two (2) hours will be granted upon receipt of Warranty Claim Form.

PIPER AIRCRAFT CORPORATION, LOCK HAVEN, PA., U.S.A.