



# SERVICE LETTER *No. 589*

Piper Aircraft Corporation

Lock Haven, Pennsylvania, U.S.A.

August 18, 1971 M

---

Subject: Stainless Steel Fuel Selector Valve Housing (Reference Piper Service Spares Letter No. SP-282 dated November 15, 1968)

Models Affected: PA-30 Twin Comanche

Serial Numbers Affected: 30-1 to 30-1744 incl.

Compliance Time: Recommended at the next 100 hour inspection or annual inspection, or at the next 50 hour or 90 day fuel filter bowl draining and cleaning procedure, whichever occurs first.

Purpose: To provide an improved design fuel selector valve housing, featuring a conical shaped stainless steel bowl which improves drainage of moisture and sediment from the fuel system.

This product advancement item was previously announced on Piper Service Spares Letter No. SP 282, dated November 15, 1968. Since that time, our records indicate that approximately 25% of the above referenced aircraft owners and operators have taken advantage of this fuel system improvement feature. To encourage PA-30 owners and operators to take advantage of this fuel system improvement feature, this item is being made available to the field at a special reduced price for one year duration (from this Service Letter Effectivity Date).

Instructions: Not applicable.

Material Required: One (1) each (per fuel selector valve assembly) Piper Kit No. 757 187, Fuel Selector Valve Housing Replacement (kit includes stainless steel housing, gasket, "O" ring and attaching hardware).

Availability of Parts: Your Piper Dealer.

Effectivity Date: This Service Letter is effective August 23, 1971.

Summary: Please contact your Piper Dealer for details concerning price and availability and to take immediate advantage of this offer.